

Appendix 2

Photographs from residents showing existing changes to Accordia



001



002



003



004



005



006



007



008



009



010



011



012



013



014



015

Key

- 001-004 voids being in filled to create internal rooms
- 008-009 contrasting timber treatments
- 010-011,013 replacement of copper down pipes with plastic
- 014-015 screen of balconies