The Trumpington Conservation Area - Draft Appraisal: Summary of Responses

- 1 = action taken
- 2 = not within the remit of this document
- 3 = no action taken

NB: Where the same comments have been made by different methods, these have only been included once e.g. where emails are making the same points as Comments Forms.

	Respondent	Comment		Response		Action	
1	English Heritage East of England Region	(i)	extensions welcomed. Possibility of extending further along Grantchester Road to include the terrace, as well as the front gardens which have been included, should be considered. Also the crescent of shops and flats should be considered as part of the expansion of the mid-twentieth century. They are also integral to the open space in front which been put forward for inclusion.	(i)	The area along Grantchester Road has been included as part of the open space leading into Trumpington, rather than as part of its developed area. Therefore we are not proposing to include the terrace. The proposal to include the shops and flats at the crescent is considered to be appropriate and the boundary has been altered accordingly.	(i)	1
		(ii)	It would be helpful if the descriptions were enhanced to include greater analysis of character features, building types and materials. This could be done graphically and include historic maps.	(ii)	Noted	(ii)	3
		(iii)	More information should be put in under 9.4 to give greater detail regarding what could be subject to Article 4 Directions.	(iii)	Noted	(iii)	1
		(iv)	Guidance could be offered to show how the conservation area could be managed positively in the future.	(iv)	It is felt that this is covered within the Guidance section.	(iv)	3
		(v)	The impact of the Trumpington Meadows development should be addressed more fully within the document.	(v)	Noted	(v)	1
2	Natural England	No specific	comments	Noted		3	

3	Cambridge Past, Present & Future	(i)	The issue of the existing conservation area being designated as 'at risk' by English Heritage has not been addressed within the document. Recent renewal of village sign and proposals for the war memorial are steps to improvement and other potential enhancements should be clearly listed and priorities highlighted to achieve available funding.	(i)	Text added to document to highlight this matter.	(i)	1
		(ii)	Strongly recommend inclusion of Byron's Pool with terrace on Grantchester Road.	(ii)	The Community Reserves Officer has been consulted and it was agreed that having Byron's pool within the conservation area would not give it any additional protection.	(ii) (iii)	3
		(iii)	3.7 Trumpington was not just an agricultural	(iii)	Text added	()	•
			setting but horticultural too.	()		(iv)	1
		(iv)	3.8 approaches into Trumpington important, especially the pasture in front of Anstey Hall Farm barn, Hauxton Road trees and	(iv)	Text added regarding area by Anstey Hall Farm barn. The other approaches are considered to be appropriately	()	
			Shelford Road.		documented.	(v)	3
		(v)	3.13 Trumpington Hall & Estate colour scheme within village	(v)	Noted	(vi)	3
		(vi)	3.18 further milestone by Wingate Way should be included with London Road	(vi)	Outside of proposed area	(VI)	
			description.			(vii)	1
		(vii)	5.4 War Memorial description needs to	(vii)	Text amended		
			include importance of Dr Wingate.			(viii)	3
		(viii)	A glossary is needed for more unusual	(viii)	Noted and may be used in future	<i>(</i> ,)	
		(:-)	terminology.	(:)	documents	(ix)	3
		(ix)	5.25 to 5.36 the boundary at the end of	(ix)	The inclusion of the gate to Fawcett		
			Alpha Terrace should include the gate of		School is not thought to be necessary. The other point is noted.		
			Fawcett School and a description should be added. Tree cover and enhancement		other point is noted.		
			opportunities should be described.			(x)	1
		(x)	6.11 and 9.9 it should be made clear that	(x)	Text amended.	(^)	'

1	1				1	
		there are two cemeteries in Trumpington.				
		The one at the junction of Shelford Road				
		and Hauxton Road should not be described				
		as tranquil due to its location. However St				
	(s.i)	May and St Nicholas could be.	(s.i)	These views are surrently not soon by the	(54)	2
	(xi)	6.12 south-westerly vistas of Anstey Hall	(xi)	These views are currently not seen by the	(xi)	3
		should be denoted as significant so that the		public and are obscured by trees and		
		Trumpington Meadows development can enhance this view.		hedging. The comment is noted.	(vii)	2
	(viii)		(vii)	Noted	(xii)	
	(xii)	9.11 there needs to be a feasibility study undertaken to link the proposal for 20mph	(xii)	Noted		
		as a city wide scheme.			(xiii)	2
	(xiii)	9.3 and 9.12 the enhancement of some	(xiii)	Noted	(XIII)	_
	(****)	front gardens would be beneficial. This	(7111)	Noted		
		could be run as a wider campaign or			(xiv)	2
		competition.	(xiv)	Noted	(XIV)	_
	(xiv)	A more detailed wildlife appraisal is	(XIV)	Noted		
	(7.1.7)	required.				
	(xv)	9.4 and 9.5 would welcome a detailed	(xv)	Noted	(xv)	3
	, ,	discussion to introduce the usage of Article	()		,	
		4 Directions in all conservation areas in the				
		city. Essential to have a set of photographic				
		and other records as a baseline to be				
		regularly reviewed.				
	(xvi)	9.6, 9.7, 9.3 and 9.12 there should be	(xvi)	Noted	(xvi)	3
		opportunities to improve existing and				
		introduce new larger scale landscape				
		vegetation.				
	(xvii)	9.8 seating and street furniture should be	(xvii)	Noted	(xvii)	2
		integrated throughout the village, including				
		outside of the conservation area to ensure				
	,	coherent and appropriate enhancements.	,	N. C. I	,	
	(xviii)	9.10 a review should be undertaken of	(xviii)	Noted	(xviii)	2
	(viva)	signage.	(5.65.4)	Natad	(sds.)	2
	(xix)	9.13 share concerns about Anstey Hall	(xix)	Noted	(xix)	3
		Farm Buildings which are significant to the				

		(xx)	setting of the village. 9.14 a maserplan should be prepared and highlighted with the development opportunities within the historic core of the village between Church Lane and Maris Lane, and also near to Lambourn Close. The maps should be labelled to add key road and building names to improve legibility. Long views of the church spire	(xx)	Noted These will be added to the final document where possible.	(xx)	1
4	Trumpington	The appra	should be added from Clay Farm. isal is a very helpful report which is warmly				
'	Residents'	welcomed	·				
	Association and Trumpington Local History Group	(i)	There was a low turnout at the exhibition which should not be seen as lack of interest. Perhaps it could have been more actively publicised.	(i)	Noted	(i)	3
		(ii)	8.8 surprised that Alpha Terrace was not included in the previous boundary review and support its proposed inclusion now. It is an attractive area, overwhelmed by parked cars and traffic to and from Fawcett School.	(ii)	Noted	(ii)	3
		(iii)	8.9 the inclusion of the open green in front of the crescent is supported.	(iii)	Noted	(iii)	3
		(iv)	8.12 Crossways House, 103 to 107a High Street and Allen Court are supported in principal but further thought should be given about the need to include 105 and 107 as there is a mistake in the dating of these as 17 th century in 4.14, but they are correctly described as 20 th century on page 35. Do not believe Allen Court to be worthy of inclusion.	(iv)	The incorrect dating is noted and will be altered in the text. The building is still considered to be worthy of inclusion as is Allen Court which is of historic interest as well being of interesting design.	(iv)	1
		(v)	The boundary should be extended to include Byron's Pool.	(v)	See comments above	(v)	3
		(vi)	9.5 would welcome regular monitoring and photographic surveys.	(vi)	Noted	(vi)	3

		(vii) 9.8 believe area around the War Memorial would benefit from improved paving and	(vii)	2
		provision of information panels. (viii) 9.10 recognise that the signage and street furniture is necessary but is it inconsistent and the High Street would benefit from higher quality fittings and a more integrated approach. May be more appropriate to	(viii) 2
		pursue once the new transport links are in use. Village could also benefit from new directional signs. (ix) 9.11 do not think a 20mph speed limit is realistic. Should be reviewed in 3-5 years after the opening of the Addenbrooke's Road and Guided Bus. (ix) Noted	(ix)	3
5	Cambridgeshire County Council -	(i) 2.5 Regional Spatial Strategies have been revoked. (i) Reference to this document has been removed.	een (i)	1
	Environment	(ii) Comments regarding historical development of the village. (iii) Noted	(ii)	3
		(iii) The aspiration for a 20mph speed limit is one the County would share. (iii) Noted	(iii)	3
6	Cambridgeshire County Council -	(i) Comments regarding the historical (i) Noted development of the area.	(i)	3
	Highways	(ii) 4.36 to 4.40 until the number of motor vehicles is significantly reduced, the signage is required. The impression is given that the street is cluttered with useless signs and crossing places whereas they are kept to a minimum.	(ii)	3
		(iii) 8.5 design of street furniture is often stipulated by national government. There are limited funds.	(iii)	3
7	Environment Agency	There are no objections to the review in principle. Noted	3	

8	5 Comments Sheets	All respon	dees supported the appraisal and its contents.				
	received following	They also	made the following comments:				
	public consultation	(i)	Reservations about the introduction of a	(i)	Noted	(i)	3
			20mph speed limit.				
		(ii)	The cottages on the High Street (105 and	(ii)	See comments above	(ii)	3
			107) have been greatly altered and have				
			modern houses in the front, therefore				
			should they be included?				
		(iii)	Trumpington Conservation Area as been	(iii)	See comments above	(iii)	1
			designated as an area 'at risk' and this is				
			not fully addressed in the document.				
		(iv)	The private and commercial properties	(iv)	See comments above	(iv)	3
			along the High Street should be tidied up.				
		(v)	No mention of the Anstey Way estate the	(v)	Considered, but not thought worthy of	(v)	3
			open area of which should be preserved.		inclusion		
			The Trumpington Orchard is also an asset				
			for local people.				
		(vi)	There should be speed cameras on	(vi)	Noted	(vi)	3
			Grantchester Road				