

Appendix 1



Poor replacement doors



Loss of front yard & boundary



Satellite dish



Brick detail painted over.



Front boundary removed for car parking



Porch extension