

**Inspection Results**

Inspection  
Scores

Location	A	B	C	D	Comments
<b>South General Locations May 2013 cleaning cycle</b>					
Ainsdale			3		Marks left on the outside of some window panes. Outside cills not cleaned.
Anstey Way			1		Outside cills not cleaned.
Arran Close			1		Outside cills not cleaned.
Ashbury Close		1	3		Outside cills not cleaned.
Colville Road			3	2	Outside cills not cleaned
Davy Road		3			Adhesive left on window from old notices.
Fanshawe Road		2			Outside cills dusty.
Highdene			1	1	
Monkswell			1		
Rush Grove			1	2	
St. Bede's Crescent			3	1	No evidence of window cleaning in block starting at number 38 St, Bede's Crescent
<b>Sheltered Schemes July 2013 cleaning cycle</b>					
Ditton Court			2		Window adjacent to stair lift cleaned. Front window of lounge partially cleaned. Upper windows and cills not cleaned. Cobwebs on windows not removed. Water streaks left on windows. One of the residents spoke to the inspectors about the poor state of the window cleaning. The windows on the street side do not appear to have been cleaned.
Ditchburn Place		2	2	1	Small windows on the top floor not cleaned. Cleaning on the front is very good. The standard of cleaning at the back of the building is not good.
Mansel Court			1		Outside windows are left with water streaks. Residents told the inspectors they are not happy with the standard of window cleaning. One resident quoted the example of bird droppings still left on a window after 2 years.
Rawlyn Court			2	1	No evidence of window cleaning at the back of the property.
Whitefriars		1	1		Cleaning of the main entrance windows is good. Cleaning of the upstairs back windows is poor.

<b>North General Locations August 2013 cleaning cycle</b>					
Arbury Court			1		
Brackley Close			2		Broken windows in the stairwell of block 38 to 48
Cockerel Road			3		Writing in blue on entrance door window. A resident commented that this has been there for months.
Edgecombe			2	1	Side windows on the stairs not cleaned. Covered in cobwebs.
Hawkins Road		2			Windows and cills clean.
Hazelwood Close			1	2	Windows very badly marked.
Maitland Avenue				2	Cobwebs and streaks on windows. No evidence of recent cleaning of some windows
Molewood Close				2	
Mortlock Avenue			1	2	
Rutland Close			2		Broken windows.
St. Kilda Avenue			2		